

Consider bin store for bins

3a Upgrade storage outside church. Recent storage audit suggests that the storage cupboard needs to be bigger than the boiler cupboard and that the shed outside needs to be 12'x10'

to do or longer if we continue to use the church with a consequent increase in costs.

Following the meeting of the PCC September 2019 all items except those in red boxes below were agreed as being essential. Linked items are numbered e.g. 1a, 1b... and are in boxes of the same colour. The number does not imply priority, the letter does. Items which can be progressed independently are shown in Green boxes. Changes, additional details and comments from and since the November PCC meeting are in red.

Consideration given to removing pews in chancel. However cost, possible problems with floor, having to mark their position in some way and we need to know success or otherwise of Resurrection Chapel reordering experiment before acting

Glaze in the Resurrection Chapel. Glass will need to be cut around monument. NO for Issues of cost, disabled access, safeguarding

Put in a mezzanine floor to provide a room in church. Need glazing and must move projector NO for Issues of cost, stairs decreasing circulation space, disabled access, safeguarding

Move High Altar forward to allow celebration from behind. May require making step wider to support it. Defer to later date